

# UFS Corporation

330 North 400 East  
Valparaiso, IN 46383-9704 USA  
PH: 219-464-2027 FAX: 219-464-8646  
www.ufsc.com  
Email: service@ufsc.com

## Service Reference

### Topic: Frame ME Cells, 3 Person carry at all times

*Please read carefully before performing work*


#### Required Materials

- None

#### Required Tools

- None

ME Cells used in Frame ED paint systems can be very long. The correct method to carry these long ME Cells is with 3 persons at all times.



**Think and act in a safe manner.** Always disconnect power and use a lockout before you work on the E-coat system, or any of the related subsystems. Observe any confined space conditions. Use the appropriate safety equipment & clothing for the task.

Please read all the instruction listed below to familiarize yourself with the project before attempting to perform any of the work.

1 person must be at the PVC Cap (bottom portion of the Cell, another person at the middle point where 2 x PVC Collars join the two membrane portions together, and the third person at the Bulkhead or top end.

As the 3 persons move the Cell, always hold the Cell only at the PVC portions.

**For more information** see the original manual that came with the equipment or else call UFS at the phone number shown above.