

Service Reference - Membrane Electrode

Topic: Proper Lifting of Long Crates

The pictures show proper lifting technique of crates of 10 feet or more. Failure to follow the recommended instructions will cause damage to crate.

Picture 1

Shows that two pallet jacks must be used to move the crate. Using only a forklift will cause damage to shipment.



Picture 2

Proper position of one pallet jack.



Picture 3

Proper position of second pallet jack.

UFS Corporation. . .dedicated to providing quality, innovative solutions to the electrocoating industry.

Topic: Proper Lifting of Long Crates

The pictures show proper lifting technique of crates of 10 feet or more. Failure to follow the recommended instructions will cause damage to crate.

UFS Corporation
330 North 400 East
Valparaiso, IN 46383 USA

Think and act in a safe manner. Always disconnect power and use a lockout before you work on the E-coat system, or any of the related subsystems. Observe any confined space conditions. Use the appropriate safety equipment and clothing for the task.

Phone: 219-464-2027
Fax: 219-464-8646
Email: info@ufsc.com

©UFS Corporation 2002

